

Factory data reset

1. Why do you need to restore factory Settings.


The machine cannot be used normally, some or all functions fail. The reason is that the user accidentally changed the firmware parameters.

2. Operational process

Double-click the icon below to install the software. All the options in the installation process will be default until the installation is complete.

arduino-1.0.5-r2-windows 2016/3/31 18:27 应用程序 53,829 KB

3. Open the file sketch_jan05a → sketch_jan05a.ino




4. Set the parameters

Tools→Programmer→Arduino as ISP


Tools→Serial Port→COMx

Tools→Board→Arduino Nano w/ATmega328


5. Click on the button



6. Open the file




7. Select the file




Select the file according to the control board type

☐ GRBL_2CNC_2.5.03.hex	2019/11/2 10:52	HEX 文件	83 KB
☐ GRBL_2CNC_2.5.04.hex	2019/10/28 10:00	HEX 文件	83 KB
☐ GRBL_3CNC_V3.3.hex	2019/1/12 18:04	HEX 文件	83 KB
☐ GRBL_3CNC_V3.4.hex	2019/10/17 16:58	HEX 文件	83 KB


8.



9. COMx



10.



11. Close the software, complete!